

# Estero Roofing

## Repair Report

Number: 1009

PO #:

Start Date: 3-16-22

Finish Date: 3-16-22

**Facility:** Hurricane Bay Facility  
708 Fishermans Wharf,  
Ft. Myers, FL 33931  
**Contact:** Sam Fisher - (239) 854-6244

**Bill To:** Dixie Fish Company  
714 Fisherman's Wharf,  
Ft. Myers Beach, FL 33931  
**Contact:** Erving Lambert - (239) 233-8837

**Type of Service:** Repair

**Total Price:** \$500

**Forman:** Steve Pifer

### Scope of Work:

Find cause of leak and repair.



F-102 Field Membrane - puncture/Hole/tear # 1

All holes in the membrane are considered high severity due to their high leak potential.



F-102 Field Membrane - puncture/Hole/tear # 2

All holes in the membrane are considered high severity due to their high leak potential.

# Work Order

Work Order #: 1009



F-102 Field Membrane - puncture/Hole/tear # 3

All holes in the membrane are considered high severity due to their high leak potential.



Completed Repair # 4

Repaired membrane puncture.



Completed Repair # 5

Repaired membrane puncture.



Completed Repair # 6

Repaired membrane puncture.